### BS ISO 3547-3:2017



## **BSI Standards Publication**

# Plain bearings — Wrapped bushes

Part 3: Lubrication holes, grooves and indentations



This is a preview. Click here to purchase the full publication.

#### National foreword

This British Standard is the UK implementation of ISO 3547-3:2017. It supersedes BS ISO 3547-3:2006 which is withdrawn.

The UK participation in its preparation was entrusted to Technical Committee MCE/12, Plain bearings.

A list of organizations represented on this committee can be obtained on request to its secretary.

This publication does not purport to include all the necessary provisions of a contract. Users are responsible for its correct application.

© The British Standards Institution 2017. Published by BSI Standards Limited 2017

ISBN 978 0 580 94008 8

ICS 21.100.10

## Compliance with a British Standard cannot confer immunity from legal obligations.

This British Standard was published under the authority of the Standards Policy and Strategy Committee on 31 March 2017.

#### Amendments/correction issued since publication

Date Text affected

This is a preview. Click here to purchase the full publication.

# INTERNATIONAL STANDARD

BS ISO 3547-3:2017 ISO 3547-3

Third edition 2017-02

## Plain bearings — Wrapped bushes —

Part 3: Lubrication holes, grooves and indentations

Paliers lisses — Bagues roulées —

Partie 3: Trous de graissage, rainures de graissage et creux de graissage



Reference number ISO 3547-3:2017(E)

This is a preview. Click here to purchase the full publication.



#### © ISO 2017, Published in Switzerland

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office Ch. de Blandonnet 8 • CP 401 CH-1214 Vernier, Geneva, Switzerland Tel. +41 22 749 01 11 Fax +41 22 749 09 47 copyright@iso.org www.iso.org